



2000 Series Mini Stations

Monitor microclimates with up to 4 external sensor ports. You can customize your WatchDog network, using different sensors based on the data you want to collect and analyze for optimal system performance.

- Same power, flexibility, and accuracy as the 2000 Series Weather Stations
- Measure temperature, humidity, quantum light, and more (varies by model)
- Customize your Mini Station with 1 to
 4 plug-in sensors to meet your needs
- Custom measurement intervals
- Reliable NEMA-4 type IP 66 enclosure and weatherproof connectors
- 12-month battery power source (four AA alkaline batteries included)

How do you access the data?

- **1. SpecConnect**: Wireless or Cellular Communication: Access real time data from your PC, tablet or smart phone
- **2. Direct Connect:** Download from the station to your PC. Requires SpecWare Basic or Pro
- **3. Data Shuttle:** Transport data from your station to your PC. Requires SpecWare Basic or Pro







Model 2475 Plant Growth Station

- Ideal for greenhouses includes sensors for quantum (PAR) light, air temperature, dew point, relative humidity, with 1 available external sensor port
- Computes and displays Daily Light Integral (DLI), dew point and degree days; live display of current light and cumulative light over the day
- Computes and displays DIF Average day/night temperatures differences
- Computes and displays VPD Vapor Pressure Deficit

3686WD Model 2475 WatchDog® Weather Station

Model 2450 Temperature/RH Station

- Measures air temperature, relative humidity, dew point, with 2 available external sensor ports
- Computes and displays dew point

3684WD Model 2450 WatchDog® Weather Station



Model 2400 External Sensor Station

- Ideal where multiple sensor measurements are required for temperature, soil moisture, crop canopy light, or leaf wetness data
- Plug in up to 4 external sensors

3685WD Model 2400 WatchDog® Weather Station



 Use the LCD display to check current and daily high/low readings without a PC

Model 2425 Temperature Station

- Measures air temperature with 3 available external sensor ports
- Plug in up to 3 external sensors

3683WD Model 2425 WatchDog® Weather Station

Sensors	2475	2450	2425	2400	Specifications	Accuracy
Air Temperature	✓	✓	~	OPT	-40° to 257°F (-40° to 125°C)	±0.54°F at -40° to 185°F(±0.3°C at -40° to 85°C)
Relative Humidity	✓	✓			0% to 100%	±2% at 32° to 176°F(0° to 80°C)
Dew Point	~	✓			-99° to 140°F (-73° to 60°C)	±4°F (±2°C)
Quantum Light (PAF	₹) 🗸	OPT	OPT	OPT	0 to 2500 μmol·m ⁻² ·s ⁻¹	±5%
External Sensor Port	s 1	2	3	4		
Available ports for SMEC 300 Sensors	1	2	3	4		