
Watch Dog A-Series Data Loggers

The most affordable way to track environmental conditions for analysis.

- Log 4,000 to 8,000 intervals in failsafe EEPROM data memory
- Water-resistant case (IP65 for A150 and A110, IP54 for A125 and A130); A160 is for indoor use only and must be protected from moisture
- Removable soft caps keep ports clear of debris
- Includes CR2 battery, 12-month life (except A160, which requires AC power; international adapter included)

How do you access the data?

- LCD display confirms logger operation and displays last sensor readings
- Hook up A-Series Loggers to your computer with PC Connection cable (see below), requires SpecWare Basic or Pro
- Select measurement intervals from 1 to 120 minutes
- Direct connect requires SpecWare Basic or Pro plus A-Series PC Cable (see below)





3611A



3612A





	DESCRIPTION	INTERNAL SENSOR	INTERVALS	RADIATION SHIELD	
	MODEL A160 3611A	AIR TEMPERATURE RH, CO ₂	5,333	INDOOR USE ONLY (NO SHIELD AVAILABLE)	
	MODEL A150 3612A	AIR TEMPERATURE RELATIVE HUMIDITY	5,333	OPTIONAL	
	MODEL A130 3610A	AIR TEMPERATURE EXTERNAL LEAF WETNESS	4,000	INCLUDED	
	MODEL A125 3617A	AIR TEMPERATURE EXTERNAL TEMPERATURE	4,000	RECOMMENDED	
	MODEL A110 3618A	AIR TEMPERATURE	8,000	OPTIONAL	

3661A WatchDog® A-Series PC Connection Cable - USB Port

(required to download data)

3663A Radiation Shield (needed for outdoor use)

B-Series Data Loggers

Space efficient and inexpensive logging technology.

- Ideal for shipping containers or situations where multiple areas need to be monitored
- Choose from temperature-only or temperature/humidity models
- Water resistant (IP56) stainless steel case
- Select measurement intervals from 1 to 120 minutes
- Log 2,000 to 8,000 intervals
- Integral non-replaceable battery

How do you access the data?

•Snap the B-Series Data Loggers into the Docking Station and connect it to your PC to see data. Requires SpecWare Basic or Pro

DESCRIPTION	INTERNAL SENSOR	INTERVALS	LCD DISPLAY	
MODEL B102 T/RH 3621WD Temp Range: -4 to 185°F Temp Accuracy: ±1.1°F fr Humidity: 0 to 100%, ±5%	rom 5 to 149°F (±0.6°C froi	4000 m -15 to 65°C)	NO	
MODEL B101 8K 3620WD Range: -40 to 185°F (-40 Accuracy: ±1.1°F from 5 to	TEMPERATURE) to 85°C) to 149°F (±0.6°C from -15 f	8000 to 65°C)	NO	
MODEL B100 2K 3619WD Range: -40 to 185°F (-40 Accuracy: ±1.8°F from -2 Use included plastic bag	NO			

Docking Station

3655K1 WatchDog® B-Series Docking Station - USB Port

(required to download data)







Ideal for soil temperature