

# WatchDog® 2000 Series Weather Stations



Monitor, record and analyze over a dozen environmental parameters directly from your field, orchard, vineyard or golf course

## What makes our WatchDog® Weather Stations different?

- Expand your measurement options with customizable external sensor ports
- Use the onboard LCD display to check your current and daily readings
- Choose measurement intervals from 1 to 60 minutes
- Log your data in fail-safe, non-volatile memory
- Powered by four AA batteries (included), also compatible with lithium batteries
- Compatible with WatchDog Retriever & Pups Network



## How do you access the data?

- 1. SpecConnect:** Wireless or Cellular Communication: Access real time data from your PC, tablet or smart phone
- 2. Direct Connect:** Download from the station to your PC. Requires SpecWare 9 Pro software
- 3. Data Shuttle:** Transport data from your station to your PC. Requires SpecWare 9 Pro software

## Model 2900ET

- The most powerful package for optimizing your irrigation and IPM decisions
- Measures wind direction, wind speed, air temperature, relative humidity, dew point, rainfall, solar radiation, evapotranspiration, with 5 available external sensor ports

3350WD2

WatchDog® 2900ET Weather Station

Model 2900ET  
Shown with  
optional Solar  
Power Package

Solar Power  
Option

3999WD Solar  
Power Package

Includes 5W  
solar panel  
and 6V 4.5 AH  
rechargeable  
battery



WATCHDOG 2000 SERIES WEATHER STATION FEATURES						
Sensors	2900ET	2700	2550	2800	Specifications	Accuracy
Wind Direction	✓	✓	✓		1°	±3°
Wind Speed	✓	✓	✓		0, 1 to 200 mph (0, 1 to 322 km/h)	±2 mph (±3 km/h), ±5%
Air Temperature	✓	✓	✓	OPT	-40° to 257°F (-40° to 125°C)	±0.54°F at -40 to 185°F (±0.3°C at -40+85°C)
Relative Humidity	✓	✓	✓		0% to 100%	±2% at 32° to 176°F (0° to 80°C)
Dew Point	✓	✓	✓		-99° to 140°F (-73° to 60°C)	±4°F (±2°C)
Rainfall	✓	✓		OPT	0.01 in (0.25 mm)	±2% at < 2 in (5 cm) per hour
Solar Radiation	✓	OPT	OPT	OPT	0 to 1500 W/m <sup>2</sup>	±5%
Evapotranspiration	✓					
External Sensor Ports	5	6	6	8		
Available ports for SMEC 300 Sensors	1	2	2	2		
Operating temperature range: -22 to 130°F (-30 to 55°C)						

## Additional Models



### Model 2700

- Affordable and versatile solution for growers, researchers, and consultants
- Measures wind direction, wind speed, air temperature, relative humidity, dew point, rainfall, with 6 available external sensor ports

3340WD2 WatchDog® 2700  
Weather Station



### Model 2550

- Ideal for fast, on-demand deployment without measuring rainfall
- Measures wind direction, wind speed, air temperature, relative humidity, dew point, with 6 available external sensor ports

3320WD2 WatchDog® 2550  
Weather Station



### Model 2800

- Ideal where multiple sensor measurements are required for temperature, soil moisture, crop canopy light, or leaf wetness data
- Plug in up to 8 external sensors, plus 1 optional rainfall sensor

3345WD2 WatchDog® 2800  
Weather Station